## J. P. SEEBURG CORPORATION . 1500 Dayton St., Chicago 22, Illinois

Rec. July 23/56 of .

Cofunto IRT eal. 2 TE. Eal. 2 R.C.Ed. 4 BW Nan.

July 20, 1956 Bulletin DC56-29

of BW Nan.

5 JK. Winnifers

6 MF Portage

7 AS med that

8 L.B. Leth.

9 CW Ed.
10 GL Ed.

TO ALL SEEBURG DISTRIBUTORS:

## Attention: Service Managers

Current shipments of the V-200 are set up with the "S" contact of the mechanism clamp arm switch opened wide enough to be ineffective in normal operation. We recommend that this contact be adjusted in the field for effective use if it is so desired and that it be adjusted so it is ineffective on units now in the field if there is no objection to doing so.

This recommendation is made in the belief that problems due to insecure or incorrect record clamping are being misinterpreted as intermittent failure of the Tormat Selection System.

Sincerely yours,

J. P. SEEBURG CORPORATION

CMS :BC

Manager of Field Service

1