



SERVICE SLANTS

YOUR QUESTIONS OR COMMENTS ON "SERVICE SLANTS"
ARE WELCOME AT ANY TIME

ISSUED BY WURLITZER SERVICE DEPT., NORTH TONAWANDA, N. Y.

Culpe

Models 1600, 1650, 1500A, 1550A

SUBJECT: Microphonic amplifier condition

Recent checks, on occasional microphonic conditions, have caused us to advise that such a condition in any of the above model phonographs may reasonably be caused by loose spaces at the top of the elements of the type 12AU7 tube. We therefore suggest that an R.C.A. 12AU7 tube be used in this position. This tube is provided with a double mica spacer at the top, which provides extra rigidity and greater support surface, and will, according to tests, give far superior performance.

5C022254

W-259