

SERVICE SLANTS

YOUR QUESTIONS OR COMMENTS ON "SERVICE SLANTS"
ARE WELCOME AT ANY TIME

ISSUED BY WURLITZER SERVICE DEPT., NORTH TONAWANDA, N. Y.

SUBJECT: Model 1900 Ventilation

In some cases it may be found that early Model 1900's evidence insufficient ventilation. These phonographs will be found prior to Serial Number 252700.

To relieve this situation it is suggested that the front of the upper back be cut out in accordance with the sketch below.

